

May 15, 2006

Mr. Don Stillion
Stillion Brothers Excavating, Inc.
4021 Cole Road
Perrysville, Ohio 44864

Re: **Wayne County**
Kidron Community Wastewater Treatment System
Contract A - Sanitary Sewer System

Dear Mr. Stillion:

A warranty inspection of the above referenced project was conducted on May 2, 2006 with yourself, Tim Patterson, Scott Wiggam, Jerry Herman, Allan Saline, representatives of the Wayne County Engineer's Office, Kent Baker, and myself. The following items need to be addressed in accordance with the one year guaranty.

- I. General
 - A. Repair all edge of pavements and berms that were disturbed during construction. Per Wayne County Engineer's Office, edge of pavements shall be repaired by placing asphalt along the current edge of pavement to extend the pavement to match the original edge of pavement. Then, place ODOT 304 limestone berm material adjacent to the new asphalt edge of pavement.
- II. Jericho Road
 - A. Cut window in catch basin at intersection of Zuercher Road to allow surface water to enter.
 - B. Add manhole riser to manhole in pavement near Eastwood Framing and add asphalt around casting to bring pavement to grade.
- III. Kidron Road South
 - A. Repair sunken spot in asphalt parking lot at Kidron Auction.
 - B. Repair stone drive entrance at address #5000.
 - C. Replace catch basin riser pipe with an uncut pipe section and install tee fitting in storm sewer main at address #5000.
 - D. Repair sidewalk with broken edge at address #5052.
 - E. Repair settlement and concrete drive at address #5116.
 - F. Replace (2) catch basin riser pipes with an uncut pipe section and install tee fitting in storm sewer main at address #5160.
 - G. Repair sidewalk at address #5160.
 - H. Repair settlement and grade and seed at address #5174.
 - I. Repair settlement and grade and seed at address #5190.
 - J. Repair edge of pavement and catch basin at north drive of Kidron Electric.
 - K. Repair settlement and grade and seed at address #5432.

- L. Repair settlement and grade and seed at in front of barn at address #5492.
- M. Install riser and grate on catch basin at address #5492.
- IV. Kidron Road North
 - A. Fill under sidewalk in front of Village Printing.
 - B. Raise manhole cover and grade and seed at address #4626.
 - C. Repair catch basin riser with nonshrink grout at address #4574.
 - D. Repair grading and seeding at Kidron Elementary.
 - E. Repair grading and seeding and repair catch basin riser with nonshrink grout at address #4406.
 - F. Repair grading and seeding at address #4344.
 - G. Raise manhole cover at address #4286.
 - H. Repair pipe penetration in catch basin with nonshrink grout at address #4262.
 - I. Repair concrete drive at address #4192.
 - J. Repair concrete drive at address #4196.
 - K. Repair grading and seeding at address #4162.
 - L. Repair settlement and grade and seed in front of MCC Connections.
 - M. Repair pipe penetration in catch basin with nonshrink grout at northeast corner of Hackett Road.
 - N. Repair grading and seeding at address #3464.
- V. Emerson Road West
 - A. Place additional asphalt around manhole at Kidron Auction.
 - B. Repair pavement at northwest corner of Kidron Road.
 - C. Regrade ditch to drain and grade and seed area on south side of road near Kidron Auction rear entrance.
 - D. Repair catch basin, storm pipe, and pavement at Kidron Auction rear entrance.
 - E. Repair grading and seeding at Kidron Supply.
 - F. Repair concrete drive at address #12615.
- VI. Hackett Road
 - A. Repair settlement and grade and seed at Steiner property.

If you have any comments or require additional information, please feel free to contact me.

Sincerely,

ENGINEERING ASSOCIATES, INC.

Ronny E. Portz, P.E.
Project Engineer

cc: Tim Patterson, Dept. of Environmental Services
Allan Saline, USDA Rural Development
Bill McDaid, Wayne County Engineer's Office